

CODES AND TECHNICAL STANDARDS COMMITTEE
FORMAL INTERPRETATION

REFERENCE NUMBER: 82.224.161.97.02

REFERENCE DOCUMENT: Life Safety Code 1994 Existing
13-3.2.1

LOCATION: MESCALERO SERVICE UNIT, Mescalero, NM

- QUESTIONS a) What are the construction requirements for the Medical Records room ?
b) Is the Medical Records area consider to be a Hazardous Area ?

ANSWERS: a)& b): The Medical Records room is a hazardous area according to section 13-3.2.1 of the Life Safety Code (NFPA 101).

COMMENTS: The Medical Records area shall be safeguarded by a fire barrier or an alternate extinguishing system with a smoke barrier ~~(one hour walls to the area)~~ and all the penetration in the barrier shall be filled with a material capable of maintaining the smoke resistance as per section 6-3.6.1 (b) 1. of LSC 101. dsa
Wor

Signatures:

☒ Agree
☐ Disagree


Steven L Bourn, R.A. (ES-Dallas)


5-7-97
(Date)

☒ Agree
☐ Disagree


Mark Burke, E.I.T. (ES-Dallas)


5-7-97
(Date)

☒ Agree
☐ Disagree


Gerry Shaffer, R.A. (ES-Dallas)

5/12/97
(Date)

☒ Agree
☐ Disagree


Yusuf Vora, P.E. (ES-Dallas)


5-7-97
(Date)

☒ Agree
☐ Disagree


Howard Minter, P.E. (ES-Dallas)

5/12/97
(Date)

☒ Agree
☐ Disagree


(ES-Seattle)

6-12-97
(Date)